


TROUBLE DETECTOR FOR COIL

Patent number: JP58066070
Publication date: 1983-04-20
Inventor: SAITOU SHIGERU
Applicant: MEIDENSHA ELECTRIC MFG CO LTD
Classification:
- International: G01R31/02; G05B23/02
- european: G01R31/06
Application number: JP19810164442 19811015
Priority number(s): JP19810164442 19811015

Abstract of JP58066070

PURPOSE: To handle the trouble in a coil current control circuit quickly while protecting it by detecting the disconnection and short-circuit of a coil in the circuit having a feedback circuit of a coil current.

CONSTITUTION: Disconnections of a coil 3a are possible at points A, B and C, where a short-circuit occurs at the points A and C. When a disconnection occurs, the voltage V_D of the resistance R_D zeros and the voltage V_S rises to let current I_F flow. When a short circuit occurs, the V_S falls because of $V_S = V_D$. But as current fails to flow through the coil 3a, command from a command section 1 increases and the V_D itself rises. When higher and lower levels are represented by H and L as compared with the reference value, the voltages of the coil are as shown by the table. This facilitates the determination on whether the coil is normal or in trouble.



命令 F	V_S	V_D	判定
1	H	H	正常
2	H	L	断線
3	L	H	短絡
4	L	L	正常



(19)

Generated Document.

(11) Publication number: **58066070 A****PATENT ABSTRACTS OF JAPAN**(21) Application number: **56164442**

(51) Int. Cl.: G01R 31/02 G05B 23/02

(22) Application date: **15.10.81**

(30) Priority:

(43) Date of application publication: **20.04.83**

(84) Designated contracting states:

(71) Applicant: **MEIDENSHA ELECTRIC MFG CO LTD**(72) Inventor: **SAITO HIDE**

(74) Representative:

**(54) TROUBLE DETECTOR
FOR COIL**


(57) Abstract:

PURPOSE: To handle the trouble in a coil current control circuit quickly while protecting it by detecting the disconnection and short-circuit of a coil in the circuit having a feedback circuit of a coil current.

CONSTITUTION: Disconnections of a coil 3a are possible at points A, B and C, where a short-circuit occurs at

the points A and C. When a disconnection occurs, the voltage VD of the resistance RD zeros and the voltage VS rises to let current IF flow. When a short circuit occurs, the VS falls because of $VS=VD$. But as current fails to flow through the coil 3a, command from a command section 1 increases and the VD itself rises. When higher and lower levels are represented by H and L as compared with the reference value, the voltages of the coil are as shown by the table. This facilitates the determination on whether the coil is normal or in trouble.

COPYRIGHT: (C)1983, JPO&Japio



端子	V _S	V _D	判定
1	H	H	正常
2	H	L	断線
3	L	H	短絡
4	L	L	正常

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.